

	MC type	MC type barcode	installed	Spares	Status
1	MB1-L /S-	102	29	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
2	MB1-L Ch./S-	122	1		
3	MB1-R /S+	111	29	1	at Aachen, with ROB, SB, CCB (old firmawere revision), without TRB, not cabled (?)
4	MB1-R Ch./S+	131	1		
5	MB2-L /S+	201	29	1	at CIEMAT, completely assembled (?)
6	MB2-L Ch./S+	221	1		
7	MB2-R /S-	212	29	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
8	MB2-R Ch./S-	232	1		
9	MB3-L /S0	300	58	2	at LNL on the test chambers; completely assembled
10	MB3-L Ch./S0	320	2		
11	MB4(s)-L /S+	401	8	0	spare missing (a 401 was installed instedf of a 411; the spare 401 was then installed)
12	MB4(s)-L /S-	402	8		
13	MB4(10)-L /S+	801	3		
14	MB4(10)-L /S-	802	3		
15	MB4(s)-R /S+	411	7	2	at LNL, with ROB, SB, CCB, without TRB, not cabled. One extra spare (a 401 was installed instedf of a 411; a 411 was then left as extra spare)
16	MB4(s)-R /S-	412	7		
17	MB4(10)-R /S+	811	2		
18	MB4(10)-R /S-	812	2		
19	MB4(4)-L /S0	500	4	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
20	MB4(4)-R /S0	510	6	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
21	MB4(8-12)-L /S+	601	2	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
22	MB4(8-12)-L /S-	602	2		
23	MB4(8-12)-R /S+	611	3	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
24	MB4(8-12)-R /S-	612	3		
25	MB4(9-11)-L /S0	700	5	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
26	MB4(9-11)-R /S0	710	5	1	at LNL, with ROB, SB, CCB, without TRB, not cabled
			250	14	